



UNIVERSITY OF CONNECTICUT

College of Liberal Arts and Sciences

Department of Mathematics

3D Print Support Removal Operating Procedures

- Remove 3D print from glass plate as per Ultimaker instructions.
- Wear NoCutGloves safety gloves.
- Wear safety goggles.
- Carefully use box cutter to pry and cut lose the support material.
- Retract the blade of the box cutter and put it away in the cabinet. (Report of the knife needs replacing.)
- Put the safety goggles away in the cabinet.
- Remove the gloves and put them in the cabinet. (Report if they need washing or replacement.)